




7V BATTERY HEATED OUTERWEAR SIZE CHART

| MEN'S SIZE CHART | | | | | | |
|--|---------|---------|---------|---------|---------|---------|
| A-SLEEVE LENGTH: BEND ARM SLIGHTLY & MEASURE ALONG OUTSIDE OF ARM, FROM CENTER BACK OF NECK, TO TIP OF SHOULDER, DOWN TO WRIST. B-CHEST: MEASURE AROUND FULLEST PART OF CHEST, KEEPING THE TAPE LEVEL UNDER ARMS & ACROSS BACK. C-WAIST: MEASURE AROUND THE NARROWEST PART OF THE WAIST. D-HIP: MEASURE AROUND THE FULLEST PART OF THE HIP. | | | | | | |
| SIZE | S | M | L | XL | 2XL | 3XL |
| SLEEVE LENGTH | 33" | 34" | 35" | 36" | 37" | 38" |
| CHEST | 36"-38" | 39"-41" | 42"-44" | 45"-48" | 49"-52" | 53"-56" |
| WAIST | 30"-31" | 32"-33" | 34"-36" | 38"-40" | 42"-44" | 45"-47" |
| HIP | 35"-37" | 38"-40" | 41"-43" | 44"-46" | 47"-49" | 50"-52" |



| WOMEN'S SIZE CHART | | | | | | |
|--|---------|---------|---------|---------|---------|---------|
| A-SLEEVE LENGTH: BEND ARM SLIGHTLY & MEASURE ALONG OUTSIDE OF ARM, FROM CENTER BACK OF NECK, TO TIP OF SHOULDER, DOWN TO WRIST. B-CHEST: MEASURE AROUND FULLEST PART OF CHEST, KEEPING THE TAPE LEVEL UNDER ARMS & ACROSS BACK. C-WAIST: MEASURE AROUND THE NARROWEST PART OF THE WAIST. D-HIP: MEASURE AROUND THE FULLEST PART OF THE HIP. | | | | | | |
| SIZE | XS | S | M | L | XL | 2XL |
| SLEEVE LENGTH | 31.5" | 32" | 32.5" | 33" | 34" | 35" |
| CHEST | 31"-32" | 33"-35" | 36"-38" | 39"-41" | 42"-44" | 45"-47" |
| WAIST | 24"-25" | 26"-28" | 29"-31" | 32"-34" | 35"-38" | 39"-41" |
| HIP | 33"-35" | 36"-37" | 38"-40" | 41"-43" | 44"-47" | 48"-51" |

